

DATE:-20.02.18

STRUCTURAL STABILITY CERTIFICATE

OCCUPANTS -----RABINDRA EDUCATIONAL SOCIETY


SCHOOL ADDRESS -----G-8 AREA , MAYPURI ,PLOT NO.18,TAGORE SCHOOL MAYA
PURI ROAD, NEW DELHI

THIS BUILDING HAS BASEMENT, GROUND , FIRST ,SECOND AND THIRD FLOOR .
THIS IS FRAME STRUCTUR BUILDING HAVING PROPER R.C.C. COLUMNS, BEAMS &
SLABS. ALL HAVE BEEN PROPERLY DESIGNED & CONSTRUCTED AT SITE.

THIS BUILDING HAS BEEN MAINTAINED WELL & THERE ARE NO VISIBLE
CRACKS OR ANY TYPE OF DETERIORATION TO THE STRUCTURAL PARTS OF THE
BUILDING.

THE BUILDING IS STRUCTURALLY SAFE & FIT FOR OCCUPATION. FURTHER I
CERTIFY THAT THE STRUCTURE IS CONSIDERED SAFE FOR PURPOSE IT HAS BEEN
DESIGNED FOR. THE BUILDING IS SAFE FOR ATLEAST NEXT THREE YEARS.

PRAMOD K. ARORA
Structural Engineer
M.C.D. Lic. No. SE-64
E-89, Mansarover Garden,
New Delhi-110015



P.ARORA & ASSOCIATES PVT.LTD.

PRAMOD K. ARORA
B. Sc. (Civil Engg.)
Mob. : 9810155283

PIYUSH ARORA
BE. (Civil),M tech (Struct) IIT Delhi
Mob. : 9811666949

Gurgaon Office : L2/2, DLF City Phase-II, Gurgaon, Haryana - 122002 Ph. : 0124 - 4106949, 4371361
Delhi Office : E-89, Mansarover Garden, New Delhi - 110015